

MATERIAL SAFETY DATA SHEET
Prepared according to 29 CFR 1910.1200

DATE PREPARED: May, 1991
DATE REVISED: April, 2001
0

PAGE 1
MSDS NO: 106

SECTION I - IDENTIFICATION

L&M CONSTRUCTION CHEMICALS, INC.
14851 CALHOUN ROAD
OMAHA, NE 68152

ASSISTANCE (CHEMTREC) 800-424-9300
EMERGENCY PHONE NO. 402-453-6600

ID NO.: None

PRODUCT
NAME: **L&M CURE**

DOT CLASS: None

CHEMICAL
NAME: Aqueous Silicate solution

DOT SHIPPING
NAME: None

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

INGREDIENTS	OSHA PEL	ACGIH TLV	CAS	% wt
#1: Sodium Silicate	Not Estab	Not Estab	1344-09-8	< 25

This product does not contain regulated levels of hazardous ingredients as defined in 29 CFR 1910.1200.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT (F): 214 - 216 (760 mm/hg)	SPECIFIC GRAVITY (H ₂ O = 1): 1.07
VAPOR PRESSURE (mm Hg): N/A	PERCENT VOLATILE BY VOLUME: 96
VAPOR DENSITY (AIR = 1): N/A	MELTING POINT: N/A
SOLUBILITY IN WATER: 100%	BULK DENSITY: N/A
APPEARANCE: Colorless Turbid Liquid	PH INFORMATION: 11.0 - 12.0
ODOR: Slightly Soapy	EVAPORATION RATE: N/A

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT, °F, (method used): Non-flammable
FLAMMABLE LIMITS - LEL: N/A UEL: N/A

EXTINGUISHING MEDIA: N/A

SPECIAL FIRE FIGHTING PROCEDURES: Special clothing for skin and eye protection should be worn.

SECTION V - REACTIVITY DATA

STABILITY: unstable: stable: X

INCOMPATIBILITY (materials to avoid): Avoid contact with acidic materials.

HAZARDOUS DECOMPOSITION OR BYPRODUCTS: N/A

HAZARDOUS POLYMERIZATION: may occur: will not occur: X

CONDITIONS TO AVOID: N/A

SECTION VI - HEALTH HAZARD DATA**L & M CURE**

POTENTIAL EFFECTS OF EXPOSURE (listed by primary routes of entry)

INHALATION: Exposure to mists or spray may cause coughing, sneezing, or other symptoms of upper respiratory tract irritation. Severe exposure may result in lung tissue damage.

SKIN: Will cause severe irritation on continued contact.

INGESTION: Irritation to mucous membranes of the mouth, throat, esophagus and stomach.

EYE CONTACT: Can cause severe irritation if not treated.

EMERGENCY & FIRST AID PROCEDURES

INHALATION: If symptoms are present, get person out of area to fresh air. Seek medical attention.

SKIN: Wash with plenty of water for at least 15 minutes. Remove soiled clothing and footwear. Wash clothing before reuse. Footwear should be cleaned before reuse. Seek medical attention if symptoms are present.

INGESTION: Never give anything by mouth to an unconscious person. If swallowed, do not induce vomiting. Give large quantities of water or milk, if available. If vomiting occurs spontaneously, keep airway clear. Seek medical attention.

EYE CONTACT: Object is to flush material out immediately, then seek medical attention. Immediately flush eyes with large amounts of water for at least several minutes holding lids apart to ensure flushing of the entire surface. Washing eyes 1 minute is essential. Seek medical attention.

CARCINOGENICITY OSHA: No NTP: No IARC: No

SECTION VII - PRECAUTIONS FOR SAFE HANDLING & USE

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: If a material is spilled or released, contain liquids and prevent discharges to streams or sewer systems.

WASTE DISPOSAL METHOD: Clean up action should be carefully planned and executed. Shipment, storage, and/or disposal of waste materials are regulated and action to handle spilled or released materials must meet the applicable rule. If any questions exist, contact the appropriate agencies.

PRECAUTIONS TO BE TAKEN IN HANDLING & STORAGE: Shower and eyewash facilities should be accessible.

OTHER PRECAUTIONS: Floors may become slippery when wet with L & M CURE.

SECTION VIII - CONTROL MEASURES

RESPIRATORY PROTECTION: Use local exhaust ventilation where mist may be generated.

VENTILATION: LOCAL EXHAUST: Where mists or spray may be generated

PROTECTIVE GLOVES: Standard work gloves EYE PROTECTION: Face shield

OTHER PROTECTIVE CLOTHING OR EQUIPMENT: Standard work clothing. Standard work shoes.

WORK/HYGIENIC PRACTICES: Wash contaminated clothing and dry before reuse.

END MSDS